


Banjo 222 Series Electric Pump



Models
222PIE5
222PIE51



REPLACEMENT PARTS 222 CAST IRON PUMPS W/ELECTRIC MOTORS

ITEM	PART NO	DESCRIPTION	QTY
1	17010	1/2" Jam Nut	1
2	15022	Handle	1
3	12765A	5/16-24 x 1.12 Impeller Bolt	1
4	13778	O-Ring	2
5	13777	Prime/Drain Plug	2
6	V10118	5/16" Lock Washer	9
7	15772	5 Vane Impeller	1
8	12715A	5/16-24 x 1.75 HHCS	13
9	12774VA	Impeller Bolt Gasket	1
10	12719A	Body O-Ring	1
11	12705	Check Valve	1
12	15702	Volute	1
13	15703	Rear Bracket	1
14	12902A	3/16" SQ. x 5/8" Key	1
15	12901	5/16" Flat Washer	4
16	12710	O-Ring	1
17	12717	O-Ring	4
18	12713V	Seal Assembly	1
	12713SD	Severe Duty Seal	1
19	15712	Body	1
20	17704	3/16-16 x 1.25 HHCS Bolt	8
21	17701	C-Faced Base Plate	1
22	12046	56C Adapter	1
23	V20018	3/8" Lock Washer	8
24	V20019	3/8-16 SS Hex Nut	4
25	BF107	5/16-18 x 2 1/4" HHCS Bolt	4
26	BEM5-182CZ	5 HP 3450 RPM Three Phase Motor	1
	BEM51-182CZ	5 HP 3450 RPM Single Phase Motor	1
N/S	12099	7/16-14 x 1.25" HHCS	1
N/S	15751	Bracket Shim	1
N/S	15752	Impeller Shim	1
N/S	15000	Repair Kit EPDM (Items 4, 7, 9-11, 14, 16-18, 12099, 15751 & 15752)	-
N/S	15000V	Repair Kit FKM Viton (Items 4, 7, 9-11, 14, 16-18, 12099, 15751 & 15752)	-
N/S	15999	Seal Kit EPDM (Items 4, 9-11, 14, 16-18, 12099, 15751 & 15752)	-
N/S	15999V	Seal Kit, Viton FKM (Items 4, 9-11, 14, 16-18, 12099, 15751 & 15752)	-

NOTE: EPDM gaskets, seals and o-rings used in the following assemblies unless otherwise noted: 222PBI, 222PIHY, 222PI5, 222PIH5, 222POI. Pumps equipped with FKM (viton type) also available.

Spray Advantage